

SITE INSPECTION REVIEW FORM

SITE NAME: FRANN PAPER CORPORATION  
ALIASES: STAHL EYE ASSOCIATES  
SITE I.D.#: NYDO62525043

<u>ITEM</u>	<u>COMPLETE ?</u>	
	<u>YES</u>	<u>NO</u>
SITE LOCATION (INCLUDING MAP)	<u>✓</u>	<u>—</u>
SITE BACKGROUND	<u>✓</u>	<u>—</u>
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	<u>✓</u>	<u>—</u>
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<u>✓</u>	<u>—</u>
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	<u>✓</u>	<u>—</u>
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<u>✓</u>	<u>—</u>
POTENTIAL FOR DIRECT CONTACT	<u>✓</u>	<u>—</u>
CONCLUSIONS + RECOMMENDATIONS	<u>✓</u>	<u>—</u>
REFERENCES	<u>✓</u>	<u>—</u>

HRS PRE-SCORE: PRELIMINARY SCORE = 4.57  
PROJECTED SCORE = 12.93



**COMMENTS:**

Although there are significant groundwater  
use targets, there is no indication of  
waste mismanagement (ie spills) NFRAP

REVIEWED BY:

Kate Donnelly

DATE:

9/90

\*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS